

CPR Plumbing

(210) 491-2777

PO Box 11, Helotes, TX 78023

Fax- 210-646-0086

cprplumbing1@aol.com

05/24/10

JOB#: 49000
NAME: HAPPY HOMEOWNER
ADDRESS: 123 STREET
SAN ANTONIO, TX
CLAIM#: 2045569
TEST DATE: 05/23/10

SHOWER PAN TEST

For this report, a shower pan test is described as follows:

The shower pan is tested below the tile or marble floor by plugging the drain and filling the pan with water as close as possible to the top of the threshold. The water level is marked on the shower and then monitored for a period of 60 minutes. A drop in water level indicates the shower pan is leaking. **If this report indicates the test was terminated due to water appearing, the shower pan test has failed and the water is leaking to the point that the plumber had to terminate testing to prevent further damage.**

*A shower with a fiberglass base does not have a pan. The base acts as a pan, therefore this type of testing on a fiberglass base shower determines if leaks exist at the drain connection and/or in the fiberglass base itself.

Bath#: 1

Was shower pan/base leaking? Yes X No

Type of shower X Tile Marble X Fiberglass
(WALLS) (BASE)

Size 3 X 3

Amount of loss 0 " Length of test 60 minutes

NOTES: SHOWER PAN TEST HELD. SHOWER DOOR LEAKS.