

# CPR Plumbing

(210) 491-2777

PO Box 11, Helotes, TX 78023

Fax- 210-646-0086

cprplumbing1@aol.com

05/24/10

JOB#: 49000  
NAME: HAPPY HOMEOWNER  
ADDRESS: 123 STREET  
SAN ANTONIO, TX  
CLAIM#: 2045569  
TEST DATE: 05/23/10

## LEAK LOCATION

\*\*\*\*\*The drain system was approximately located and tested with it's layout shown on the attached drawing. The numbers of each test represent the location on the attached drawing. The results of each segment of the test are as follows:

Test #	Description/ Location	Leak	If yes, loss/minute	Notes:
1	PARTIAL KITCHEN	NO		
2	WASHER AND PARTIAL KITCHEN	YES	FILLS AND DROPS OUT OF SITE IN 10 MINUTES	SOFTENER DRAIN DISCHARGES TO WASHER VENT AND IS NOT PROPERLY CONNECTED.
3	BATH #2 TUB	YES	FILLS AND DROPS OUT OF SITE IN LESS THAN 5 MINUTES	VISIBLE SEPARATION HERE.
4	BATH #1 SHOWER	YES	FILLS AND DROPS OUT OF SITE IN 8 MINUTES	
5	BATH #2 TOILET, LAVATORY, BATH #1 TUB, TOILET, LAVATORY, PARTIAL KITCHEN AND WASHER AND EXITING TRUNK	NO		BATH #1 TOILET FLANGE IS NOT SOLDERED. BATH #2 TOILET FLANGE IS ELEVATED ABOVE FLOOR.

Number of leaking segments: 3

**NOTES: VISUAL INSPECTION OF YARD SEWER SHOWS A SEPARATION AT APPROXIMATELY 10' OUT FROM CLEAN OUT, BACKFALL FROM 11' TO 19' AND BACKFALL AGAIN AT 33' TO 59' AT CITY MAIN.**

Craig Cooper, President

M-18637