

CPR Plumbing

(210) 491-2777

05/24/10

PO Box 11, Helotes, TX 78023

Fax- 210-646-0086

cprplumbing1@aol.com

JOB#: 49000
NAME: HAPPY HOMEOWNER
ADDRESS: 123 STREET
SAN ANTONIO, TX
CLAIM#: 2045569
TEST DATE: 05/23/10

FLOW TEST

For this report, a flow test is described as follows:

A pre-measured amount of water is induced into each fixture's drain and is recaptured at the house drain exiting the foundation.

The water is then re-measured to see if there was a loss of water from entry and discharge points.

This test duplicates normal conditions.

	Amount of water induced:	Amount of water recovered:	TOTAL LOSS/ GAIN:
<u>BATH #1</u>			
SHOWER:			
Test #1	640 OZ	630 OZ	-10 OZ
Test #2	640 OZ	630 OZ	-10 OZ
WATER CLOSET:			
Test #1	640 OZ	640 OZ	0 OZ
Test #2	640 OZ	640 OZ	0 OZ

BATH #2

TUB:

Test #1	640 OZ	640 OZ	0 OZ
Test #2	640 OZ	640 OZ	0 OZ

KITCHEN SINK:

Test #1	640 OZ	640 OZ	0 OZ
Test #2	640 OZ	640 OZ	0 OZ

WASHER:

Test #1	640 OZ	624 OZ	-16 OZ
Test #2	640 OZ	624 OZ	-16 OZ